

モンゴル・ウランバートル市営バス
排ガス削減プロジェクト（実証事業）開始しました！

2019年10月30日～



黒煙テストの様子（右から3人目・手前が弊社代表）



車両と取付写真

Diesel Test Report

Uaanbaatar Mongolia

Report number: 0112217
 Date and time: 10/19/2019 13:00
 Vehicle number: KMJTA18BP8C015004
 Engine temperature (Oil): # 56 °C
 Idle rpm: 400 - 1200 rpm

	RPM	K
Measurement 1	--	6.70
Measurement 2	--	8.87
Measurement 3	--	2.88
Average value	--	6.15
Range	0	5.99
Overall result	Not OK	
Limit values	Cut-off rpm 2200 - 4000 rpm	K average <= 1.20 K range <= 0.00

Emission tester serial number: (AU)
 Operator identification: K356

Signature and seal

Diesel Test Report

Uaanbaatar Mongolia

Report number: 0112218
 Date and time: 10/19/2019 13:11
 Vehicle number: KMJTA18BP8C015004
 Engine temperature (Oil):
 Idle rpm: 400 - 1200 rpm

	RPM	K
Measurement 1	--	8.07
Measurement 2	--	1.38
Measurement 3	--	0.41
Average value	--	3.29
Range	0	7.66
Overall result	Not OK	
Limit values	Cut-off rpm 2200 - 4000 rpm	K average <= 1.20 K range <= 0.00

Emission tester serial number: MAHA MDO2-LON (AU V 6.00/1.29.GB)
 Operator identification: K188

Signature and seal

1 BUS

取付前 6.15 (m-1) → 取付後 3.29 (黒煙-46.5%)